

### DAILY CONSTRUCTION REPORT

Date: Friday, 09-15-2017

(Day 101)

PROJECT: Middle Road Improvements WEATHER: Mostly cloudy, drizzle

CLIENT:Town of CumberlandTEMP:Low 70'sCONTRACTOR:Storey BrothersWIND:CalmPROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:Humid

#### **FIELD FORCE**

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	2	Miscellaneous work near drainage easement
Ace Security		1	Flagger at each end of work zone
Construction Services & Irrigation	1		Dave Bernard, PWD Inspector

### **VISITORS**

Time	Name	Representing	Remarks		

#### **EQUIPMENT**

3 Excavators -	CAT	3161	CAT	330D	CAT	329D

- 2 Smooth Drum Rollers IR 116D, Volvo 540
- 1 Dozer CAT D5K2
- 2 Loaders CAT 930H, CAT 930M

### **TODAY'S CONSTRUCTION ACTIVITIES**

Storey Brothers worked on new slab at 55 Middle Road (not in contract).

Excavator Operator from Storey Brother worked with Sevee & Maher with test pits in "partial box cut areas."

Construction Services & Irrigation took water samples at hydrants after dechlorinating the water main extension the previous day.

## **TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES**

Resume installation of gas main in area skipped due to ledge.

Resume blasting for water main.

#### **QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

#### DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland BY: James C. Manzer, P.E., PTOE TITLE: Field Engineer
- 3 Storey Brothers, Inc.
- 4 Summit Natural Gas
- 5 Central Maine Power

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS September 15, 2017



Test Pit 3C at STA 35+30, 10' Left - Encountered ledge 18-inches below the top of the milled pavement. About 4 inches of pavement had been milled off leaving about 3 inches. This area is in a "full" box cut area.



Test Pit 9 at STA 47+50 10' Left – Did not reach ledge at a depth of 45 inches below the milled pavement. Gravel/clay interface was about 18 inches below top of the 2 inches of milled pavement remaining. This area was in a "partial" box cut area.