

707 Sable Oaks Drive, Suite 30 South Portland, Maine 04106 207.772.2515

FIELD OBSERVATION REPORT

Project: Gas Main – Cumberland-Falmouth-Yarmouth Client: Towns of Cumberland, Falmouth and Yarmouth GP Field Rep: Benjamin Grondin (BG). Weather: Cloudy Temp. Range :70-80°F Time onsite: Multiple visits GP Project No: 1636.87 Visit Date: July 12, 2017 Report Date: July 13, 2017

Summit Natural Gas

Crew #1: ETTi – Foreman (Nolan) and 4man crew Equipment: CAT mini excavator, Ditchwitch drill, Ditchwitch vacuum, I dump truck

Distribution: File, Bill Shane, Chris Bolduc, Adam Theriault, Bryan Haberman, Bryan Foster, Bert Stefanic

Work in Progress – Town of Cumberland

> Installing 4" gas main in southbound shoulder of Route 100.

Discussions & Observations

Crew #1:

<u>Route 100</u>

- Work Zone Closure: One lane closed on Route 100 with flaggers maintaining two way traffic.
- Crew installed approximately 350' of pipe from near the lower driveway of house #144 to near house #134.
- All utilities located via manhole inverts, camera, electronic locator, or hand excavated.
- > Depth of utilities are to top of pipe unless noted in table below.

| Utility | Depth |
|-----------------------|-------|
| 4" gas main | 4' |
| 1" water service #134 | 7'1" |
| 1" water service #136 | 7' |
| I" water service #138 | 5'3" |
| I" water service #144 | 5' |

- Crew backfilled trench and potholes with excavated material. Existing material was used as backfill. Backfill was compacted in lifts with a jumping jack.
- Crew placed cold patch where pavement had been removed at the corner of Spring Drive. Cold patch was used due to the proximity to a driveway culvert in an attempt to reduce erosion to the driveway culvert as well as undermining Rt.100. The remaining trenches were left gravel due to their size and location.
- > Crew clean worksite and traffic returned to normal at approximately 5:30 PM.

Upcoming Work

Continue main install on Route 100 tomorrow (6/13)



Restoration Required

| Location MAINS | Length of Main or # of Services | Roadway Crossing Trench Patch (1) | Driveway Crossing Trench Patch (1) | Longitudinal Road or Shldr Trench Patch (1) | Sidewalk Trench Patch (1) | Pave Pothole (I) | Restore Gravel Shldr or Driveway (2) | Loam, Seed & Mulch (2) | EC Blanket (2) | Riprap (2) | Moratorium Roadway Restoration (1) | Comments |
|-------------------|------------------------------------|--------------------------------------|---------------------------------------|--|---------------------------|------------------|---|------------------------|----------------|------------|---------------------------------------|-----------------------------|
| Route 100 | 350' | | | X | | x | | Х | | | | Pothole in #136 driveway |

(I) Gorrill Palmer must observe pavement during placement

(2) Gorrill Palmer will observe restoration after completion

Visitors on Site

None

Concerns or Questions

None at this time.

Follow up Required

None at this time.

Prepared By: Benjamin Grondin, El

Reviewed By: Drew Gagnon, El

If there are any discrepancies, please notify the sender immediately





Compacting second lift of gravel near lower driveway to house #144



Compacting final lift of gravel near house #134

July 12, 2017 Page 4





Compacting cold patch at corner of Spring Drive