

## FIELD OBSERVATION REPORT

Project: Gas Main – Cumberland-Falmouth-Yarmouth  
Client: Towns of Cumberland, Falmouth and Yarmouth  
GP Field Rep: Benjamin Grondin (BG)  
Weather: Sunny  
Temp. Range: 55-70°F  
Time onsite: Multiple visits

GP Project No: 1636.87  
Visit Date: October 23, 2017  
Report Date: October 24, 2017

### Summit Natural Gas

Summit Personnel: Jeff  
Crew #1: ETTi – Foreman (Matt B.) and 4 man crew  
Equipment: CAT mini excavator, 2 dump truck

Distribution: File, Bill Shane, Chris Bolduc, Adam Theriault, Bryan Haberman, Bryan Foster, Bert Stefanic

---

### Work in Progress – Town of Cumberland

- Crew #1 installing long side 1/2" gas service at #69 Skillin Road.

### Discussions & Observations

#### Crew #1:

#### 69 Skillin Road

- Work Zone Closure: Skillin Road reduced to one lane with flaggers maintaining alternating one way traffic.
- Crew started service at the house and brought the service to the roadside ditch.
- Crew ended the service at the roadside and did not cross Skillin Road. Therefore, Crew did not remove any pavement.
- All utilities located via manhole inverts, camera, electronic locator, or hand excavated.
- No utilities were crossed.
- Gas service is not parallel to any utilities therefore >6' of separation was achieved.
- Crew backfilled trench in the vegetated ditch with excavated material and gravel. Backfill was compacted in lifts with a jumping jack.
- Crew placed cold patch in the roadway crossing near #80 and #88 as rain is forecasted.
- Crew cleaned worksite and traffic returned to normal by 1:30PM.

### Upcoming Work

- To be determined.



### Restoration Required

Location	Length of Main or # of Services	Roadway Crossing Trench Patch (1)	Driveway Crossing Trench Patch (1)	Longitudinal Road or Shldr Trench Patch (1)	Sidewalk Trench Patch (1)	Pave Pothole (1)	Restore Gravel Shldr or Driveway (2)	Loam, Seed & Mulch (2)	EC Blanket (2)	Riprap (2)	Moratorium Roadway Restoration (1)	Comments
<b>MAINS</b>												
<b>SERVICES</b>												
69 Skillin	I							X				

- (1) Gorrill Palmer must observe pavement during placement  
(2) Gorrill Palmer will observe restoration after completion

### Visitors on Site

- None observed.

### Concerns or Questions

- All gravel trenches within the roadway shall be monitored and repaired or treated for dust control as necessary.
- Ditch side slopes on Skillin Road require soft restoration as they were vegetated prior to gas main install.
- Notify GP when moratorium restoration at Balsam Drive will occur.

### Follow up Required

- None at this time.

Prepared By: Benjamin Grondin, EI

Reviewed By: Drew Gagnon, EI

If there are any discrepancies, please notify the sender immediately



Cold patch in roadway crossing at 88 Skillin.



Cold patch in roadway crossing at 80 Skillin