SEVEE & MAHER ENGINEERS, INC

## DAILY CONSTRUCTION REPORT

04-20-2017 Date: (Day 4)

Overcast Lower 40's Light Breeze

Middle Road Improvements WEATHER: Town of Cumberland TEMP: Storey Brothers WIND: Dan Diffin, P.E. **HUMIDITY:** Damp

## **FIELD FORCE**

**PROJECT MANAGER:** 

CONTRACTOR:

**PROJECT:** 

CLIENT:

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1 (Rick Storey)	2 (Laborer/Operators)	Rick in Excavator. Loader & Roller by
			Laborers
Ace Security	0	4	2 Flaggers at each work zone
Thirsty Turf	1	0	Temporary water system disinfection
David Bernard	1	0	Water System Inspector for PWD

# VISITORS

Time	Name	Representing	Remarks

#### EQUIPMENT

2 Excavators – Cat 316F (drainage) & Cat 315C (hoe ram)			
1 Loader (Cat 930H) 1 Mini Excavator (Cat 305E) Roller (Volvo 540)			
3 Dump Trucks 1 Box Truck (Equipment)			
Misc.: Sweeper Attachment, Pavement Cutter, Pipe Cutter, Plate Compactor, GPS, Laser Level with Rod			

#### **CONSTRUCTION ACTIVITIES**

Resumed installation of 6-inch underdrain from CB-8B southward.

Hoe Ram needed to remove ledge (0.5 to 1 foot) from CB-8B to STA 80+50 (south of Knowles driveway)

Cored CB-8B and connected existing 12-inch underdrain flowing from Tuttle Road to improve drainage from Tuttle to CB-8B

No tree work today. Work remains from 42 Middle Road southward but is on hold until next week.

Performed clean up at end of day prior to rain predicted for Friday. No digging planned for Friday due to rain.

Plan to connect temporary services on Friday if favorable test results are received in time.

## QUALITY ASSURANCE

Inspector for PWD, David Bernard, on-site, as needed, to coordinate flushing, disinfection, and testing with Thirsty Turf. SME onsite for installation of pipe and catch basins

DISTRIBUTION:

- 1 File
- 2 SME
- 3 Town of Cumberland
- 4 Storey Brothers, Inc.
- Portland Water District 5

BY: Jim Manzer, P.E., PTOE TITLE: **Project Engineer** 

PAGE 1 OF 2



# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS April 20, 2017



Excavation & installation of 6" underdrain uphill from CB-8B southward



Late day clean-up prior to predicted rains on Friday with digging planned.

PAGE 2 OF 2