WEEKLY CONSTRUCTION REPORT

PERIOD ENDING: FRI, 19 May 2017

PROJECT: MIDDLE ROAD IMPROVEMENTS JOB NO.: 16047.00 CLIENT: TOWN OF CUMBERLAND CONTRACTOR: STOREY BROTHERS, INC. PROJECT MANAGER: DAN DIFFIN

AVERAGE FIELD FORCE Name of Contractor		Non-manual	Manual	Remarks
STOREY BROTHERS INC.		1	3	RICK STOREY,
510		1	5	CREW CHIEF
ACE SECURITY			3	FLAGGING
CONSTRUCTION SERVICES AND		1		DAVID BERNARD
IRRIGATION, INC. (CSI)				INSPECTOR FOR PWD
VISITORS				
Date	Name	Representing		Remarks
5/18	Skip McKay	СМР		Reviewing pole relocations
5/18	Eric Linquist	СМР		Reviewing pole relocations
5/18	Dennis Fasulo	PWD		Dig safe checking for pole relocations
1 to 4 EXCAV	QUIPMENT ON-SITE 'ATORs, 1- MINI EXCAVATOR JCKS FOR MATERIALS AND I	<i></i>	ER, 2-4 DUMP TI	RUCKS
CONSTRUC	FION ACTIVITIES			
	d new 12-inch underdrain from ca	(1 D CD 70 CD	7D	

5/16 – Installed new 12-inch underdrain from catch Basin CB-7B to C7A and installed 6-inch underdrain upstream of CB-7A.

5/17 – Made the final connection for the reconfigured water main connection at Middle & Tuttle in side lot of 163 Middle Road.

5/18 – Finished installation of 6-inch underdrain upstream of catch basin CB-7A.

5/19 – Installed 15" underdrain from STA 58+60, Left (just south of 116 Middle) northward to just north of 122 Middle Road.

QUALITY ASSURANCE:

PWD Inspector, on-site overseeing installation of piping and valves and connection to existing pipe in Tuttle Road. SME on-site to review erosion control, quantity verification and work on Tuttle Road

DISTRIBUTION:

- 1. Owner Town of Cumberland
- 2. Contractor Storey Brothers
- 3. Engineer Sevee & Maher Engineers, Inc.
- 4. File

BY: James, C. Manzer, P.E., PTOE

TITLE: FIELD ENGINEER

PAGE 1 OF 1 PAGE

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Construction Report-5-19-17.doc



Photograph 1: Structure for catch basin CB-7B just south of 142 Middle Road driveway.



Photograph 2: Shallow ledge as high as road subgrade at STA 73+15 in front of 146 Middle Road.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Photos 0515-0519.docx May 22, 2017 Page 1 of 5



Photograph 4: Installation of 12-inch underdrain from 142 to 140 Middle Road.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Photos 0515-0519.docx May 22, 2017 Page 2 of 5



Photograph 5: 12"x10" adapter installed on existing 10-inch water main that runs parallel to Tuttle in side yard of 163 Middle Road.



Photograph 6: Installing elbow to connect new 12-inch main from vault to the 12-inch pipe extending from the reducer pictured above.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Photos 0515-0519.docx May 22, 2017 Page 3 of 5



Photograph 7: Resuming the installation of 6-inch underdrain to terminate at stake in foreground at STA 68+80 in front of Butterworth Farm.



Photograph 8: 122 Middle Road prior to stripping and installation of 15-inch underdrain.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Photos 0515-0519.docx May 22, 2017 Page 4 of 5



Photograph 9: Outlet of 15-inch underdrain south of driveway for 116 Middle Road near STA 58+65.



Photograph 10: Placing Type D gravel backfill over 15-inch underdrain south of 122 Middle Road.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Weekly Photos 0515-0519.docx May 22, 2017 Page 5 of 5