

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

DAILY CONSTRUCTION REPORT

Date: Monday, 10-22-2018

| PROJECT: | Middle Road Improvements | WEATHER: | Clear |
|------------------|--------------------------|-----------|--------------|
| CLIENT: | Town of Cumberland | TEMP: | High 40"s |
| CONTRACTOR: | Storey Brothers | WIND: | Light Breeze |
| PROJECT MANAGER: | Dan Diffin, P.E. | HUMIDITY: | Low |

FIELD FORCE

| Name of Contractor | Supervisor | Non-Supervisor | Remarks |
|--------------------|------------|----------------|----------|
| J. Parsons Paving | 1 | 5 | Pavement |
| | | | |
| | | | |
| | | | |

VISITORS

| Time | Name | Representing | Remarks |
|------|------|--------------|---------|
| | | | |
| | | | |

EQUIPMENT

| 2 – Vibratory Plate Compactor |
|-------------------------------|
| 1 - Dump Truck |
| |
| |

TODAY'S CONSTRUCTION ACTIVITIES

-Paving driveway aprons, patches for water main installation and valve box adjustments

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

-No activity planned for tomorrow

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Jeff Read, P.E.

TITLE: Engineer

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS October 22, 2018



Photo 1 – Placing pavement for driveway apron



Photo 2 – Paving at driveway apron

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS October 22, 2018



Photo 3 – Driveway repair at water line crossing



Photo 4 – Valve stem adjustments