WEEKLY CONSTRUCTION REPORT

PERIOD ENDING: WED., 15 Nov. 2017

PROJECT: MIDDLE ROAD IMPROVEMENTS JOB NO.: 16047.00 CLIENT: TOWN OF CUMBERLAND CONTRACTOR: STOREY BROTHERS, INC. PROJECT MANAGER: DAN DIFFIN

AVERAGE FIELD FORCE


Name of Contractor		Non- manual	Manual	Remarks
STOREY BROTHERS EXCAVATING, INC.		1	3-4	On-site 11/09 through 11/15
NORTHEAST SAFETY (Flagging)		0	3	On-site 11/09 through 11/15
SUMMIT NATURAL GAS		0	0	-
CONSTRUCTION SERVICES AND IRRIGATION		1	0	On-site 11/13 and 11/15
(CSI) - I	Dave Bernard, PWD Inspector			
Glidden Paving		1	7	On-site 11/13 and 11/14
Ted Berry		1	2	On – Site 11/15
VISITORS				
Date	Name	Representing		Remarks
	J IPMENT ON-SITE DRS, 1 DOZERS, 1 LOADER, & 1 RO	OLLER (Storev	Brothers)	
	rs (Glidden Paving)		2100000)	
	ON ACTIVITIES			
	Placed and graded reclaim STA 27+00	to STA 14+00.		
	e graded reclaim STA 27+00 to STA 1			
	n., 11/12 – No Work			
Mon., 11/13 – Pa	aved first layer of binder course on wes	st side of Middle	e Road from STA 49	9+50 to STA 14+00. Excavated end of
water main to pr	epare for water main pigging.			
Tues., 11/14 – P	aved first layer of binder course on eas	t side of Middle	Road from STA 49	+50 to STA 14+00. Backed up edge of
paved and drives	way entrances.			
Wed., 11/15 – W	Vorked on backing up edge of pavemen	t and driveways	s. Ted Berry on-site	to pig water main.
	CONSTRUCTION ACTIVITIES			
	Cut pavement at driveway entrances an	0 0 0		
	<u> </u>	and reset some of	culverts to help with	driveway entrances and ditch side slopes
	n., 11/19 – No Work			
	Vork on ditching and site clean-up.			
	ossible driveway paving and other pavi	ing hand work.		
Wed., 11/22– Co	ontinue site clean-up for winter.			
QUALITY ASS				
SME on-site to r	eview overall progress, verify material	s & quantities, a	and inspect erosion of	control measures.

DISTRIBUTION:


- 1. Owner Town of Cumberland
- 2. Contractor Storey Brothers
- 3. Engineer Sevee & Maher Engineers, Inc.
- 4. File

BY: Nick Thompson

TITLE: FIELD ENGINEER PAGE 1 OF 1 PAGE



\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Photos\Weekly Photos 1109-1115.docx November 16, 2017 Page 1 of 5



\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Photos\Weekly Photos 1109-1115.docx November 16, 2017 Page 2 of 5



\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Photos\Weekly Photos 1109-1115.docx November 16, 2017 Page 3 of 5



\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Photos\Weekly Photos 1109-1115.docx November 16, 2017 Page 4 of 5



Photograph 10 – Wednesday, November 15th – Backing up pavement and driveway entrances.

\\nserver\CFS\TCU\Middle Road\Construction\Weekly Reports\Photos\Weekly Photos 1109-1115.docx November 16, 2017 Page 5 of 5