

ENVIRONMENTAL. CIVIL . GEOTECHNICAL . WATER . COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

### DAILY CONSTRUCTION REPORT

Date: Wednesday, 06-13-2018

PROJECT:	Middle Road Improvements	WEATHER:	Clear
CLIENT:	Town of Cumberland	TEMP:	High 70"s
CONTRACTOR:	Storey Brothers	WIND:	8-10 mph
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	High

#### **FIELD FORCE**

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	4	Loam, seed, and mulch
Maine Drilling and Blasting	1	2	1 – Drill Rig
Ace Security		5 Flaggers	Flaggers for clean-up and drilling operations

#### VISITORS

Time	Name	Representing	Remarks

## EQUIPMENT

2 - Excavators
1 – Roller
1 - Sweeper
1 - Loader
1 – Tractor with mulcher

### TODAY'S CONSTRUCTION ACTIVITIES

Crew continued clean-up (loam, seed, and mulch) of disturbed areas from Range Way to Waterfall Way.

Maine Drilling and Blasting on site to continue blasting bedrock for water main just north of Evergreen Lane toward the Falmouth town line near 17 Middle Road.

## TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Continue loam, seed, and mulch toward the area where construction stopped last fall near Evergreen Lane Continue blasting for water main toward the Falmouth Town line.

#### QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

#### DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Nick Thompson

TITLE: Field Engineer

## SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS June 13, 2018



Photo 1 – Removing blasting mats after a blast



Photo 2 – Cleaning up area after a blast

## SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JUNE 13, 2018



Photo 3 - Loam, seed, and mulch around Range Way



Photo 4 – Loam, seed, and mulch across the road from Range Way

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JUNE 13, 2018



Photo 5 – Mulching in front of 53 Middle Road



Photo 6 - Loam and seed 45 Middle Road

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JUNE 13, 2018



Photo 7 – Cleaning up after blasting for the day



Photo 8 – Drill holes for blasting the next day