

**DAILY CONSTRUCTION REPORT**

Date: Thursday, 06-14-2018

**PROJECT:** Middle Road Improvements  
**CLIENT:** Town of Cumberland  
**CONTRACTOR:** Storey Brothers  
**PROJECT MANAGER:** Dan Diffin, P.E.

**WEATHER:** Clear  
**TEMP:** High 70's  
**WIND:** 8-10 mph  
**HUMIDITY:** High

**FIELD FORCE**

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	4	Loam, seed, and mulch
Maine Drilling and Blasting	1	2	1 – Drill Rig
Ace Security		5 Flaggers	Flaggers for clean-up and drilling operations

**VISITORS**

Time	Name	Representing	Remarks

**EQUIPMENT**

2 - Excavators
1 – Roller
1 - Sweeper
1 - Loader
1 – Tractor with mulcher

**TODAY'S CONSTRUCTION ACTIVITIES**

Crew continued clean-up (loam, seed, and mulch) of disturbed areas from Waterfall Way to Evergreen Lane
Maine Drilling and Blasting on site to continue blasting bedrock for water main just north of Evergreen Lane toward the Falmouth town line near 17 Middle Road.

**TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES**

Continue loam, seed, and mulch toward the area where construction stopped last fall near Evergreen Lane
Continue blasting for water main toward the Falmouth Town line.

**QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

**DISTRIBUTION:**

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Nick Thompson

TITLE: Field Engineer

SEVEE & MAHER ENGINEERS, INC.  
CONSTRUCTION PHOTOS  
June 14, 2018



Photo 1 – Removing blasting mats after a blast



Photo 2 – Placing loam near Evergreen Lane



SEVEE & MAHER ENGINEERS, INC.  
CONSTRUCTION PHOTOS  
JUNE 14, 2018



Photo 3 – Loam, seed, and mulch in front of 34 Middle Road



Photo 4 – Loam, seed, and mulch in front of 34 Middle Road



SEVEE & MAHER ENGINEERS, INC.  
CONSTRUCTION PHOTOS  
JUNE 14, 2018



Photo 5 – Raking loam just before Evergreen Lane



Photo 6 – Loam, seed, and mulch in front of 41 Middle Road



SEVEE & MAHER ENGINEERS, INC.  
CONSTRUCTION PHOTOS  
JUNE 14, 2018



Photo 7 – Drilling for blasting holes



Photo 8 – Cleaning up after a blast