

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

DAILY CONSTRUCTION REPORT

Date: Thursday, 07-19-2018

PROJECT:	Middle Road Improvements	WEATHER:	Clear
CLIENT:	Town of Cumberland	TEMP:	Low 80"s
CONTRACTOR:	Storey Brothers	WIND:	Calm
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	Low

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	4	Water service installation
Ace Security		3 Flaggers	Flaggers

VISITORS

Time	Name	Representing	Remarks	

EQUIPMENT

3 - Excavators			
2 – Roller			
1 - Sweeper			
1 - Loader			
1 – Bull Dozer			

TODAY'S CONSTRUCTION ACTIVITIES

-Storey Brothers crew excavated to subgrade for full depth road reconstruction and placed subbase gravel from STA 14+00 to STA 10+50.

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Continue excavation for full depth road reconstruction.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Nick Thompson

TITLE: Field Engineer

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS July 19, 2018



Photo 1 – Excavating to subgrade for full depth road reconstruction



Photo 2 – 350 feet on the east side of Middle Road complete

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 19, 2018



Photo 3 – Excavating to subgrade and placing fabric for full depth road reconstruction



Photo 4 – Compacting subgrade

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 19, 2018



Photo 5 – West side of Middle Road at STA 10+50, ending point for the day



Photo 6 – Grading subbase gravel

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 19, 2018



Photo 7 – Placing subbase gravel STA 11+00




Photo 8 – Compacting subbase gravel