

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

DAILY CONSTRUCTION REPORT

Date: Friday, 07-20-2018

PROJECT:	Middle Road Improvements	WEATHER:	Clear
CLIENT:	Town of Cumberland	TEMP:	Low 80"s
CONTRACTOR:	Storey Brothers	WIND:	Calm
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	Low

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	3	Box Cut
Ace Security		3 Flaggers	Flaggers

VISITORS

Time	Name	Representing	Remarks

EQUIPMENT

3 - Excavators		
2 – Roller		
1 - Sweeper		
1 - Loader		
1 – Bull Dozer		

TODAY'S CONSTRUCTION ACTIVITIES

-Storey Brothers crew excavated to subgrade for full depth road reconstruction and placed subbase gravel from approximately STA 10+50 to 8+00

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Continue excavation for full depth road reconstruction.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Nick Thompson

TITLE: Field Engineer

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS July 20, 2018



Photo 1 – Compacting subbase gravel near STA 8+00



Photo 2 – Compacting subbase gravel

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 20, 2018



Photo 3 – Grading subbase gravel near existing bus turnaround



Photo 4 – Excavating to base grade on east side of Middle Road

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 20, 2018




Photo 5 – Checking base grade for full depth construction



Photo 6 – Compacting base material

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 20, 2018



Photo 7 – Placing fabric over base grade before gravel placement



Photo 8 – Excavating for full depth road reconstruction