

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

DAILY CONSTRUCTION REPORT

Date: Tuesday, 07-24-2018

PROJECT:	Middle Road Improvements	WEATHER:	Overcast
CLIENT:	Town of Cumberland	TEMP:	Low 80"s
CONTRACTOR:	Storey Brothers	WIND:	Calm
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	High

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	3	Box Cut
Ace Security		3 Flaggers	Flaggers

VISITORS

Time	Name	Representing	Remarks

EQUIPMENT

3 - Excavators
2 – Roller
1 - Sweeper
1 - Loader
1 – Bull Dozer

TODAY'S CONSTRUCTION ACTIVITIES

-Storey Brothers crew removed pavement, excavated to subgrade for full depth road reconstruction, and placed subbase gravel from approximately STA 6+50 to 4+00

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Continue excavation for full depth road reconstruction near Tall Pines Way.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

BY: Nick Thompson

TITLE:

Field Engineer

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS July 24, 2018



Photo 1 – Placing and compacting subbase gravel



Photo 2 – Preparing to switch sides

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 24, 2018



Photo 3 – Compacting subbase gravel in front of 10 Middle Road



Photo 4 – Excavating to base grade near 15 Middle Road

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 24, 2018



Photo 5 – Excavating to base grade near 15 Middle Road



Photo 6 – Checking base grade and placing fabric

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 24, 2018



Photo 7 – Grading subbase gravel



Photo 8 – Excavating for gravel placement