

### **DAILY CONSTRUCTION REPORT**

Date: Tuesday, 07-31-2018

**PROJECT:** Middle Road Improvements **WEATHER:** Clear **CLIENT:** Town of Cumberland TEMP: Low 80"s **CONTRACTOR:** Storey Brothers WIND: Calm PROJECT MANAGER: Dan Diffin, P.E. **HUMIDITY:** High

#### **FIELD FORCE**

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	3	Base Gravel
Ace Security		3 Flaggers	Flaggers
Glidden Paving	1	9	Paving

### **VISITORS**

Time	Name	Representing	Remarks

## **EQUIPMENT**

EQUI MENT
3 - Excavators
2 – Roller
1 - Sweeper
1 - Loader
1 – Bull Dozer
1 – Paver (Glidden Paving)

### **TODAY'S CONSTRUCTION ACTIVITIES**

105/11 0 00/10/1/01/1/11=0				
-Glidden Paving on site to place first 2 inch layer of 19mm binder on Middle Road STA 0+00 to 14+00				

#### TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

No work on site	

## **QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

## DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland BY: Nick Thompson TITLE: Field Engineer
- 3 Storey Brothers
- 4 Summit Natural Gas
- 5 Portland Water District

## SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS July 31, 2018



Photo 1 – Paving bus turnaround at 4 Middle Road



Photo 2 – Beginning paving at the Falmouth Town Line

## SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 31, 2018



Photo 3 – Beginning paving at the Falmouth Town Line



Photo 4 – Placing pavement in front of 4 Middle Road

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 31, 2018



Photo 5 – Compacting pavement



Photo 6 – Compacting pavement

## SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS JULY 31, 2018



Photo 7 – Beginning east side travel lane at STA 14+00



Photo 8 – Paving east site travel lane near Tall Pines Way