

DAILY CONSTRUCTION REPORT

Date: Thursday, 08-10-2017

(Day 77)

PROJECT:Middle Road ImprovementsWEATHER:SunnyCLIENT:Town of CumberlandTEMP:Low 80s

CONTRACTOR:Storey BrothersWIND:Calm to light breezePROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:Slightly Muggy

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	4	Trucking and Labor support during
			Pavement Milling. Remedial road work
Ace Security		2	1 Flagger at each grinding work zone
Coastal Road Repair	1	1	Wirtgen pavement grinder

VISITORS

Time	Name	Representing	Remarks

EQUIPMENT

- 2 Excavator CAT 290D & CAT 316F
- 1 Loader Volvo 930H
- 1 Dozer CAT D5K2
- 1 Roller Ingersoll SD116DX

Idle - Komatsu pc78us Mini-excavator, Deere 970 Tractor (w/ Harper-Goossen SB5400 Straw Blower) FLEXIROC Percussion Rock Drill (owned by McGoldrick for blasting ledge)

TODAY'S CONSTRUCTION ACTIVITIES

Started day milling pavement (8'2" wide and 3 ½" deep) in the south bound lane in a southerly direction starting from STA 49+50 (at 95 Middle Road) to STA 25+00 (at 50 Middle Road).

Turned milling machine around and milled approximately 4 feet of remaining pavement on the western shoulder in a northerly direction.

Switched alternating 1-way traffic lane to the west side of the road and milled the northbound lane in a southerly direction back to STA 25+00.

Turned milling machine around and milled pavement on the eastern shoulder in a northerly direction to the southern extent of blasting near STA 35+00.

Storey Brothers prepared the road for 2-way traffic and the 3 day pause in construction (Friday, Sat., & Sun.).

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

No road or waterline work planned for Friday, August 11th. Lucas Tree Service to do light trimming prior to 11AM.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland BY: Jim Manzer, P.E., PTOE TITLE: Field Engineer
- 3 Storey Brothers, Inc.
- 4 Summit Natural Gas
- 5 Central Maine Power

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS August 10, 2017



Beginning of 8'2' wide x 3 $\frac{1}{2}$ inch deep pavement milling in southbound travel lane at STA 49+50 (near 95 middle Road) looking southward.



Milling shoulder of southbound lane in a northerly direction and conveying the millings onto trucks. These millings will be used later on the road as the top layer of gravel.