

ENVIRONMENTAL • CIVIL • GEOTECHNICAL • WATER • COMPLIANCE

DAILY CONSTRUCTION REPORT

Date: Friday, 08-28-2017

(Day 89)

PROJECT:Middle Road ImprovementsWEATHER:Sunny & clearCLIENT:Town of CumberlandTEMP:Mid 70sCONTRACTOR:Storey BrothersWIND:Light breeze

PROJECT MANAGER: Dan Diffin, P.E. HUMIDITY: Low

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	3	Installing water line
McGoldrick Brothers Blasting	1	2	Drilling and blasting ledge for water line installation
Ace Security		3 Flaggers	1 Flagger at each end of work zone plus "Breaker".
Jim's Tree Service	1	2	Clearing edge of right-of-way.

VISITORS

Time	Name	Representing	Remarks
9AM	Jay Arnold	PWD	Checking water main installation and service locations

EQUIPMENT

2 Smooth Drum Rollers - IR 116D, Volvo 540

1 Dozer - Deer 550H

2 Loaders - CAT 930H, CAT 930M

McGoldrick - 1 FLEXIROC Percussion Rock Drill

Jim's Tree Service - Bobcat Mini-Excavator, Chevy Bucket Truck, Vermeer BC1500 Chipper

TODAY'S CONSTRUCTION ACTIVITIES

Storey Brothers installed approximately 378 lineal feet of water line from STA 34+56 to STA 30+78. Roadway in the work area was watered for dust control.

McGoldrick Brothers drilled and blasted ledge for water service installation.

Tree crew cleared edge of right-of-way north of STA 7+00

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Continue water line installation.

Drill and Blast for water main and water service installation.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

1 SME

2 Town of Cumberland BY: James C. Manzer, P.E., PTOE TITLE: Field Engineer

- 3 Storey Brothers, Inc.
- 4 Summit Natural Gas
- 5 Central Maine Power

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS August 28, 2017



Extremely shallow ledge at STA 34+50.



Backfilling after water main installation near STA 33+50.