SEVEE & MAHER ENGINEERS, INC



ENVIRONMENTAL • CIVIL • GEOTECHNICAL • WATER • COMPLIANCE

DAILY CONSTRUCTION REPORT

Date: Wednesday, 06-07-2017 (Day 34)

PROJECT:	Middle Road Improvements	WEATHER:	Sunny, Clear
CLIENT:	Town of Cumberland	TEMP:	Low 70's
CONTRACTOR:	Storey Brothers	WIND:	Calm to Light
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	Dry

### FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1 (Owner & Lead Excavator Operator)	3 Operator/Laborers	Earthwork support to Summit
Summit Natural Gas	0	3 Installation Technicians	To install 4-inch plastic gas main
On-Target	1	2	1 rig installing replacement poles

### VISITORS

Time	Name	Representing	Remarks

#### EQUIPMENT

2 Excavators – CAT 316F (used excavate for gas line)		
CAT 330D (reserved removing ledge with hoe ram)		
CAT 315D (backfilling)		
1 Loader - Cat 930H (used to move material/equipment and sweeping)		
1 Roller – Ingersoll SD116DX (idle)		
1 Dozer – CAT D5k2 (idle but to remain on-site for road work)		

### **CONSTRUCTION ACTIVITIES**

Resumed trench excavation at STA 74+90 across from 147 Middle Rod (Soule) about 60 feet north of Pole 335.

Excavated behind CB-7C. New Pole 335 not placed yet

Excavated southward to 146 Middle Road (Peterson) driveway with relatively little ledge.

Replacement Pole #334 previously placed by pole crew so gas trench was located between the new and existing poles.

Replacement Pole #333 previously placed by pole crew so gas trench was located behind new pole.

Finished the day south of the Lewis driveway (140 Middle Road) near STA 70+75.

#### QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

# DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 Storey Brothers, Inc.
- 4 Summit Natural Gas
- 5 Central Maine Power

BY: Jim Manzer, P.E., PTOE TITLE: Project Engineer

PAGE 1 OF 2

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS June 7, 2017



Less ledge helped crew reach Peterson driveway (146 Middle Road) by mid-moring.



End of day of gas line installation from STA 71+75 looking back towards Pole 333. Gas line trenched behind catch basin CB-7A infront of Lewis driveway (140 Middle).

PAGE 2 OF 2