



ENVIRONMENTAL • CIVIL • GEOTECHNICAL • WATER • COMPLIANCE

DAILY CONSTRUCTION REPORT

Date: Friday, 05-12-2017
(Day 17)

PROJECT: Middle Road Improvements
CLIENT: Town of Cumberland
CONTRACTOR: Storey Brothers
PROJECT MANAGER: Dan Diffin, P.E.

WEATHER: Partly cloudy
TEMP: Mid 50s
WIND: Steady Breeze
HUMIDITY: Damp

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1 (Rick Storey)	3 (Laborers)	Laborers operate equipment as needed
Ace Security	0	3 (Flaggers)	1 Flagger at each end of work zone

VISITORS

Time	Name	Representing	Remarks

EQUIPMENT

3 Excavators – CAT 316F (used to install underdrain) CAT 315C (used for strip and rough grade swales) CAT 330D (used to remove ledge in trench with hoe ram attachment)		
1 Loader - Cat 930H (used to transport backfill material, equipment, etc.)		
1 Roller - Volvo 540		
1 Bulldozer – CAT D5K2 LGP (idle in morning used to place Type D gravel in afternoon)		
2 Dump trucks	1 Box Truck (Equipment)	1 Box Truck (Materials)

CONSTRUCTION ACTIVITIES

Installed CB-7C
Installed CB-7D (Type F) in front of driveway to 147 Middle Road and 12-inch storm drain connecting it to CB-7C
Removed existing 12-inch underdrain and installed new 12-inch underdrain at new edge of pavement upgradient from CB-7C towards CB-7B
Cleaned up and stabilized area in preparation of the weekend.

QUALITY ASSURANCE

SME on-site to review overall progress, verify materials & quantities, and inspect erosion control measures.
Disinfection results came back favorable for reconfigured water main connection at Middle & Tuttle. Work to complete connection can continue.

DISTRIBUTION:

- 1 File
- 2 SME
- 3 Town of Cumberland
- 4 Storey Brothers, Inc.
- 5 Portland Water District

BY: Jim Manzer, P.E., PTOE TITLE: Project Engineer

SEVEE & MAHER ENGINEERS, INC.
CONSTRUCTION PHOTOS
May 12, 2017



Structure for Catch Basin CB- 7C installed nearly entirely in ledge.



Picture taken at CB-7C depicting the saw cutting diagonally across pavement prior to the installation of CB-7D that outlets to CB-7C

SEVEE & MAHER ENGINEERS, INC.
CONSTRUCTION PHOTOS
May 12, 2017



Ledge exposed near STA 75+00 across from 147 Middle Road on back slope of swale



Grubbing and rough grading west side of road from Butterworth Farm looking northward.