

DAILY CONSTRUCTION REPORT

ENVIRONMENTAL • CIVIL • GEOTECHNICAL • WATER • COMPLIANCE

Monday, 05-08-2017 Date:

(Day 13)

PROJECT: Middle Road Improvements **WEATHER:** Overcast, Drizzle **CLIENT:** Town of Cumberland TEMP: Upper 40's **CONTRACTOR:** WIND: Storey Brothers Light Breeze Dan Diffin, P.E. **PROJECT MANAGER: HUMIDITY:** Damp

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1 (Rick Storey)	3 (Laborers)	Laborers operate equipment as needed
Ace Security	0	2 (Flaggers)	1 Flagger at each end of work zone
CSI (for PWD)	1 (Dave Bernard)	0	Dave Bernard, Inspector for PWD

VISITORS

110110110			
Time	Name	Representing	Remarks

EQUIPMENT

1 Excavators – Cat	316F (active in work zone)			
1 Loader - Cat 930H – Used to transport backfill material, equipment, etc.				
1 Roller Volvo 540				
2 Dump trucks	1 Box Truck (Equipment)	1 Box Truck (Materials)		

CONSTRUCTION ACTIVITIES

CONSTRUCTION ACTIVITIES
Resumed the replacement (renewal) of existing water services on west side "long side" of road heading north.
Replaced 1 service then encountered ledge on the second service taking most of the day to install.
Treated reconfigured water main connection at Middle & Tuttle with chlorine solution for 24-hour disinfection.

QUALITY ASSURANCE

PWD Inspector, Dave Bernard coordinated with the homeowners about turning off & on the water for the service replacements. SME on-site to review overall progress, verify materials & quantities, and inspect erosion control measures

BY:

Jim Manzer, P.E., PTOE

TITLE:

DISTRIBUTION:

PAGE 1 OF 2

Project Engineer

1 File

2 **SME** 3

Town of Cumberland

- Storey Brothers, Inc.
- Portland Water District

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS May 8, 2017



Water service installed at 142 Middle Road by pulling new line under road.



Preparing to remove ledge to install water service at 146 Middle Road