

# DAILY FIELD OBSERVATION REPORT

Project: Route I Roadway Improvements

Client: Town of Cumberland GP Field Rep: Benjamin Grondin (BG)

GP Field Rep: Benjamin Grondin (BG)

Report Date: March 29, 2017

Weather: Cloudy

Temp. Range: 37-47°F

GPCEI Project No: 1636.83

Visit Date: March 29, 2017

Time onsite: 8:15 am - 9:30 am (BG), 12:45 pm - 1:15 pm (BG)

Shaw Brothers:

Personnel – Supervisor: Josh Fairweather(JF), 2 laborers, 1- Excavator Operator, 4 Flaggers

(Sub)

Equipment – I- Komatsu PC 360 Excavator, I- John Deere 450H Dozer, I- Cat CS66 roller,

I-Cat M318D Rubber Tire Excavator, 6 - Trucks

Distribution: File, Bill Shane, Chris Bolduc

## **Work in Progress**

Crew performed 800' LF of box cutting in the left lane beginning at +/- sta. 118+50 through +/- sta. 110+50. Crew also placed and compacted base gravel in the box cut.

#### **Discussions/Observation**

- > 8:15 am BG on site. Crew had set up traffic control and had begun excavation in the left lane.
- ➤ Lane Closure SB lane closed from +/- sta. 120+00 to +/- sta. 114+00. 3 flaggers maintaining traffic.
- > 8:15 am 9:30 am Crew continued box cut and backfill in left lane near +/- sta 118+50. JF had no questions or concerns for BG at this time.
- $\triangleright$  9:30 am BG off site.
- ➤ 12:15 pm − 1:15 pm − BG documented a "Right Shoulder Closed" sign near +/- sta. 147+50. Cones and barrels were placed at the edge of pavement between the travel way and closed shoulder.
- > 1:15 pm 1:30 pm Crew continuing boxcut near +/- sta. 113+50. JF had no questions or concerns for BG at this time.
- $\triangleright$  1:30 pm BG off site.

#### Schedule of Work

> Pavement removal and box cutting to resume on 3/30/17.

### **Visitors on Site**

None at this time

#### **Concerns/Questions**

None

#### Follow up Required

None

Prepared By: Benjamin Grondin, El
Reviewed By: Doug Reynolds, PE

If there are any discrepancies, please notify the sender immediately



Photo I – Compacting shoulder prior to placing gravel



Photo 2 – Signage near +/- sta. 150+00



Photo 3 – Gravel shoulder from +/- sta. 144+65 to +/- sta. 130+00 protected by cones and barrels