

Project: Route I Roadway Improvements Client: Town of Cumberland GP Field Rep: Benjamin Grondin (BG) Weather: Sunny Time onsite: 8:15 am - 9:15 am (BG), 2:30 pm - 3:45 pm (BG) Shaw Brothers: Personnel – Supervisor: Josh Fairweather(JF), 2 laborers, 2- Operators, 4 Flaggers (Sub) Equipment – I- Komatsu PC 360 Excavator, I- John Deere 450H Dozer, I- Cat CS66 roller, I-Cat M318D Rubber Tire Excavator, 6 - Trucks

GPCEI Project No: 1636.83 Visit Date: March 30, 2017 Report Date: March 30, 2017 Temp. Range: 37-47°F

File, Bill Shane, Chris Bolduc Distribution:

## Work in Progress

> Crew performed 600' LF of box cutting in the left lane beginning at +/- sta. 110+50 through +/- sta. 104+50. Crew also placed and compacted base gravel in the box cut.

# **Discussions/Observation**

- 8:15 am BG on site. Crew had set up traffic control and had begun excavation in the left lane near +/- sta. 110+50.
- Lane Closure SB lane closed from +/- sta. 118+00 to +/- sta. 102+00. 3 flaggers maintaining traffic.
- 8:15 am 9:15 am Crew continued box cut and backfill in left lane near +/- sta 110+50. Crew removed pavement up to +/- sta. 106+00. |F had no questions or concerns for BG at this time.
- ➢ 9:15 am − BG off site.
- 2:30 pm 3:45 pm Crew continuing boxcut and backfill in left lane near +/- sta. 106+00. BG observed rough grading and compaction of base gravel materials. JF had no questions or concerns for BG at this time.
- ➢ 3:45 pm − BG off site.

# Schedule of Work

Pavement removal and box cutting to resume on 3/31/17.

# Visitors on Site

None observed.

# **Concerns/Questions**

None at this time.

# **Follow up Required**

 $\succ$  None at this time.

Prepared By: Benjamin Grondin, El

Reviewed By: Doug Reynolds, PE

If there are any discrepancies, please notify the sender immediately




Photo I – Removing pavement near +/- sta. 106+00 (Morning).



Photo 2 – Subbase graded in general conformance with typical sections (Afternoon).



Photo 3 – Placing base gravel material near +/- sta. 106+00 (Afternoon).



Photo 4 – Base gravel placed and compacted in left shoulder across from Powell Road (Afternoon).