

ENVIRONMENTAL • CIVIL • GEOTECHNICAL • WATER • COMPLIANCE

#### **DAILY CONSTRUCTION REPORT**

Date: Tuesday, 08-01-2017

(Day 70)

PROJECT: Middle Road Improvements WEATHER: Sunny slightly hazy

CLIENT:Town of CumberlandTEMP:Low 80'sCONTRACTOR:Storey BrothersWIND:Light BreezePROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:Slightly Humid

#### **FIELD FORCE**

Name of Contractor	Supervisor	Non-Supervisor	Remarks
Storey Brothers	1	2	Owner as Lead Operator, Sr. Laborer as 2 <sup>nd</sup> Operator when needed.
Ace Security		2 (plus 1 "Breaker")	1 Flagger at each end of road work zone
On Target Utility Services	1	4	2 boom trucks & crews to transfer wire onto new poles
Northeast Safety		2	1 Flagger at each end of pole work zone

#### **VISITORS**

Time	Name	Representing	Remarks
9:30 am	Skip McKay	CMP	Arranged to move Pole #339

## **EQUIPMENT**

- 1 Excavator CAT 290D Excavator (Grubbing shoulder)
- 1 Mini-Excavator Komatsu pc78us (Installing temporary water main under driveways)
- 1 Loader Volvo 930H (with sweeper attachment for sweeping up after excavator)
- Idle CAT D5K2 Dozer, Ingersoll SD116DX Roller, Deere 970 Tractor (with Harper-Goossen SB5400 Straw Blower)
- 2 Boom Trucks (Owned by On Target Utility Services to transfer electrical wires for CMP)

## **TODAY'S CONSTRUCTION ACTIVITIES**

Installed temporary water main from STA 51+21 to STA 47+80 to serve houses #95, #97, #99, & #100.

Grubbed the shoulders on both sides of the road from STA 46+50 (95 Middle Road) to STA 37+50 (76 Middle Road)

Pole crews continued to transfer electrical wires southward from the Tuttle Road end.

### TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Place loam & seed along eastern side of road north of gully

# **QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

## DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland BY: Jim Manzer, P.E., PTOE TITLE: Field Engineer
- 3 Storey Brothers, Inc.
- 4 Summit Natural Gas
- 5 Central Maine Power

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS August 1, 2017



Started day installing temporary water main from hydrant (at STA 51+21, RT) extending 350 feet southward to serve houses #95, #97, #99, & #100.



Southern extent of shoulder grubbing along both sides of the road to STA 37+50 (76 & 77 Middle Road) after installing temporary water main.