

#### **DAILY CONSTRUCTION REPORT**

Date: Monday, 05-21-2018

Clear, Sunny

**WEATHER:** 

**PROJECT:** Tuttle Road Sidewalk Extension

And Road Reconstruction

CLIENT:Town of CumberlandTEMP:High 70"sCONTRACTOR:A.H. Grover, Inc.WIND:LightPROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:Low

### **FIELD FORCE**

I ILLD I ONGL			
Name of Contractor	Supervisor	Non-Supervisor	Remarks
A.H. Grover, Inc.	1	4	Drainage Improvements and sidewalk subgrade
Project Flagging		3	

#### **VISITORS**

Time	Name	Representing	Remarks
	Dave Bernard	PWD	Inspector for water service at 280 Tuttle Rd

#### **EQUIPMENT**

Lacin Millian	
2 - Excavators	
1 – Plate Tamp	
1 - Sweeper	
1 - Loader	

#### TODAY'S CONSTRUCTION ACTIVITIES

TODAT 3 CONSTRUCTION ACTIVITIES
-Crew performed live tap and installed corporation and curb stop for 280 Tuttle Road
-Crew worked on subgrade for sidewalk extension

#### TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Crew will continue to work on sidewalk extension subgrade from Maurice Way to rail road tracks.

### **QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

## DISTRIBUTION:

1 SME

2 Town of Cumberland BY: Nick Thompson TITLE: Field Engineer

3 A.H. Grover, Inc.

4

5

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 21, 2018



Photo 1 – Working on subgrade for sidewalk



Photo 2 – Compacting sidewalk subgrade

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 21, 2018



Photo 3 – Corporation at 280 Tuttle Road installed



Photo 4 – Working on sidewalk subgrade