

## **DAILY CONSTRUCTION REPORT**

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

Date: Wednesday, 05-23-2018

Clear

PROJECT: Tuttle Road Sidewalk Extension WEATHER:

And Road Reconstruction

CLIENT:Town of CumberlandTEMP:High 70"sCONTRACTOR:A.H. Grover, Inc.WIND:LightPROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:High

### **FIELD FORCE**

TILLD I ONOL	T .	T	
Name of Contractor	Supervisor	Non-Supervisor	Remarks
A.H. Grover, Inc.	1	3	Drainage Improvements and sidewalk subgrade
Project Flagging		3	

#### **VISITORS**

Time	Name	Representing	Remarks
	Three Personal	Portland Water District	On-site to repair air release valves

#### **EQUIPMENT**

2 -	Excavators

- 1 Plate Tamp
- 1 Sweeper
- 1 Loader

### **TODAY'S CONSTRUCTION ACTIVITIES**

-Crew excavated out air release valves at both ends of the project to assist PWD with repair so PWD can shut down the water main for hydrant relocation.

-Crew had sub-contractor on site to sawcut edge of pavement so crew can install pad for curbing machine.

### **TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES**

Crew will continue to excavate and prepare subgrade for sidewalk extension

Possibly set frames and grates/covers

#### **QUALITY ASSURANCE**

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

#### DISTRIBUTION:

1 SME

2 Town of Cumberland BY: Nick Thompson TITLE: Field Engineer

3 A.H. Grover, Inc.

4

5

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 23, 2018



Photo 1 - Water service for 280 Tuttle Road



Photo 2 – Saw cutting pavement for curb installation

# SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 23, 2018



Photo 3 – Saw cutting pavement for curb installation



Photo 4 – Subgrade for sidewalk extension near Town Hall