

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

SEVEE & MAHER ENGINEERS, INC

DAILY CONSTRUCTION REPORT

Date: Friday, 05-25-2018

PROJECT:	Tuttle Road Sidewalk Extension And Road Reconstruction	WEATHER:	Clear
CLIENT:	Town of Cumberland	TEMP:	High 70"s
CONTRACTOR:	A.H. Grover, Inc.	WIND:	Light
PROJECT MANAGER:	Dan Diffin, P.E.	HUMIDITY:	High

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
A.H. Grover, Inc.	1	3	Drainage Improvements and sidewalk subgrade
Project Flagging		3	

VISITORS

Time	Name	Representing	Remarks
All Day	PWD		Inspecting fire hydrant relocation

EQUIPMENT

2 - Excavators
1 – Plate Tamp
1 - Sweeper
1 - Loader

TODAY'S CONSTRUCTION ACTIVITIES

-Crew relocated fire hydrant at STA 8+75 in front of 272 Tuttle Road.

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Crew will continue setting frames and grates/covers and working on sidewalk extension subgrade.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

- 1 SME
- 2 Town of Cumberland
- 3 A.H. Grover, Inc.
- 4 5

BY: Nick Thompson

TITLE: Field Engineer

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 25, 2018



Photo 1 – Frame and grate at CB 3 complete



Photo 2 – Frame and grate at CB 2 complete

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 25, 2018



Photo 3 – Excavating around old fire hydrant at STA 8+72 to relocate



Photo 4 – Excavating around old fire hydrant at STA 8+72 to relocate

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS MAY 25, 2018



Photo 3 – Excavating around old fire hydrant at STA 8+72 to relocate



Photo 4 – Excavating around old fire hydrant at STA 8+72 to relocate