

ENVIRONMENTAL · CIVIL · GEOTECHNICAL · WATER · COMPLIANCE

DAILY CONSTRUCTION REPORT

WEATHER:

Date: Monday, 08-27-2018

Clear

PROJECT: Tuttle Road Sidewalk Extension

And Road Reconstruction

CLIENT:Town of CumberlandTEMP:Mid 80"sCONTRACTOR:A.H. Grover, Inc.WIND:CalmPROJECT MANAGER:Dan Diffin, P.E.HUMIDITY:High

FIELD FORCE

Name of Contractor	Supervisor	Non-Supervisor	Remarks
A.H. Grover, Inc.	1	1	
Project Flagging		3	

VISITORS

Time	Name	Representing	Remarks

EQUIPMENT

1 - Excavator	
1 – Roller	
1 - Sweeper	
1 - Loader	

TODAY'S CONSTRUCTION ACTIVITIES

Place subbase gravel at Portland Water District pump station entrance, approximate STA 12+60, lt.	
Repair minor erosion at embankments on north side of Tuttle Road.	

TOMORROW'S ANTICIPATED CONSTRUCTION ACTIVITIES

Pave sidewalk and driveway aprons, STA 0+00 to STA 12+75.

QUALITY ASSURANCE

SME on-site to oversee progress, facilitate communications, and inspect erosion control measures.

DISTRIBUTION:

1 SME

2 Town of Cumberland BY: Jeff Read TITLE: Engineer

3 A.H. Grover, Inc.

4

5

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS

AUGUST 27, 2018



Photo 1 – Embankment repair north of Bunker's Way



Photo 2 – Apron preparation at PWD pump station

SEVEE & MAHER ENGINEERS, INC. CONSTRUCTION PHOTOS AUGUST 27, 2018



Photo 3 – Sidewalk base, STA 0+00, rt.



Photo 4 - Sidewalk base, STA 3+28, rt