## WEEKLY CONSTRUCTION REPORT

PROJECT: TUTTLE ROAD SIDEWALK EXTENSION AND ROAD RECONSTRUCTION JOB NO.: 15221.00 CLIENT: TOWN OF CUMBERLAND CONTRACTOR: A.H. GROVER, INC. PROJECT MANAGER: DAN DIFFIN PERIOD ENDING: WED., 16 MAY 2018

PROJECT MANAGER: DAN DIFFIN				
AVERAGE FIELD FORCE				
Name of Contractor		Non- manual	Manual	Remarks
A.H. GROVER INC		1	2-4	On-site 05/10 through 05/16
Project Flagging (Flagging)		0	3	On-site 05/10 through 05/16
LIGITODG				
VISITORS Date Name Representing Remarks				
Date	Name	Кері	resenting	Remarks
TYPICAL EQUIPMENT ON-SITE				
1-2 EXCAVATORS, 1 LOADER, 1 SWEEPER & 1 ROLLER (A.H. GROVER, INC.)				
CONSTRUCTION ACTIVITIES				
Thurs., 05/10 – Continued installing 15 inch HDPE storm drain and structures toward Town Hall				
Fri., 05/11 - Completed installation of 15 inch HDPE storm drain and structures toward Town Hall				
Sat., 05/12 & Sun., 05/13 – No Work				
Mon., 05/014 – Installed CB 1 with 15 inch outlet pipe. Extend 15 inch CMP just west of CB 1. Installed 18 inch HDPE driveway				
culvert at 272 Tuttle Road.				
Tues., 05/15 – Installed 15 inch HDPE cross pipe out of drain manhole 1 along with field inlet 2 Wed., 05/16 – Began installation of block retaining wall approximate STA 5+50 to 7+25				
weu., 05/10 – Began instantion of block retaining wan approximate STA 3+50 to 7+25				
PROJECTED CONSTRUCTION ACTIVITIES				
Thurs., 05/17 – Continue working on block retaining wall				
Fri., 05/18 – Continue working on block retaining wall and grading for sidewalk				
Sat., 05/19 & Sun., 05/20 – No Work				
Mon., 11/21 – Water service tap for 280 Tuttle Road				
Tues., 11/22 – Replace hydrant assembly at STA 8+79 just south of 272 Tuttle Road				
Wed., 11/23– Continue grading for sidewalk				
OUAL ITY ACCUDANCE.				
QUALITY ASSURANCE:				

SME on-site to review overall progress, verify materials & quantities, and inspect erosion control measures.

## DISTRIBUTION:

- 1. Owner Town of Cumberland
- 2. Contractor A.H. Grover, Inc.
- 3. Engineer Sevee & Maher Engineers, Inc.
- 4. File

BY: Nick Thompson

TITLE: FIELD ENGINEER PAGE 1 OF 1 PAGE



\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0510-0516.docx May 17, 2017 Page 1 of 5



\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0510-0516.docx May 17, 2017 Page 2 of 5



Photograph 6 - Monday, May 14<sup>th</sup> - Catch basin1 with 15 inch HDPE outlet pipe

\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0510-0516.docx May 17, 2017 Page 3 of 5



Photograph 8 - Tuesday, May 15<sup>th</sup> – Compacting cross trench at field inlet 2

\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0510-0516.docx May 17, 2017 Page 4 of 5



\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0510-0516.docx May 17, 2017 Page 5 of 5