WEEKLY CONSTRUCTION REPORT

PROJECT: TUTTLE ROAD SIDEWALK EXTENSION AND ROAD RECONSTRUCTION JOB NO.: 15221.00 CLIENT: TOWN OF CUMBERLAND CONTRACTOR: A.H. GROVER, INC. PROJECT MANAGER: DAN DIFFIN PERIOD ENDING: WED., 08 August 2018

	AGER: DAN DIFFIN			
AVERAGE FIEI				
Name of Contractor		Non- manual	Manual	Remarks
A.H. GROVER INC		1	2-4	On-site 07/26 through 08/01
Project Flagging (Flagging)		0	3	On-site 07/26 through 08/01
THOMADO				
VISITORS	Nama	Dom	······	Demontes
Date	Name Glen Miller		resenting PWD	Remarks
On-site 08/06 and 08/08	Glen Miller	1	PWD	Inspector
TYPICAL EOU	PMENT ON-SITE		I	
			CROWER INC.	
1-2 EXCAVATO	RS, 1 LOADER, 1 SWEEPER &	I KULLEK (A.H. U	JROVER, INC.)	
CONSTRUCTIO	N ACTIVITIES			
		st ends of project ar	ea along with establi	shing top of slope
Thurs., 08/02 – Crew began box cut on east and west ends of project area along with establishing toe of slope. Fri., 08/03 – Crew began installing base gravel and installed new culverts and regraded entrance at Bunkers Way				
	., 08/05 – No Work	instance new cases	no una regradete	
Mon., 08/06– Crew raised two exiting manholes and brought them up to grade				
	ew clean existing culverts to prepa			base gravel.
	ew disconnected the temporary wa			
	ONSTRUCTION ACTIVITIES			
Thurs., 08/09– Slip line existing culverts				
	n installing drainage improvemen	ts		
	., 08/12– No Work			
	ntinue drainage improvements			
	gin fine grading and placing topso			
Wed., 08/15– Cor	tinue preparing for binder pavem	ent		
	ID A MORE.			
QUALITY ASSU	RANCE: view overall progress, verify mate	1. 0		
SME on-site to re	view overall progress, verify mate	eriais & quantities, a	and inspect erosion c	ontrol measures.

DISTRIBUTION:

- 1. Owner Town of Cumberland
- 2. Contractor A.H. Grover, Inc.
- 3. Engineer Sevee & Maher Engineers, Inc.
- 4. File

BY: Nick Thompson

TITLE: FIELD ENGINEER PAGE 1 OF 1 PAGE



\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0802-0808.docx August 08, 2018 Page 1 of 4



Photograph 4 - Friday, August 3rd – New Culverts at Bunkers Way

\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0802-0808.docx August 08, 2018 Page 2 of 4



Photograph 6 - Monday, August 6th – Brining existing manhole up to grade

\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0802-0808.docx August 08, 2018 Page 3 of 4



Photograph 8 - Tuesday, August 7th – Placing base gravel