WEEKLY CONSTRUCTION REPORT

PROJECT: TUTTLE ROAD SIDEWALK EXTENSION AND ROAD RECONSTRUCTION JOB NO.: 15221.00 CLIENT: TOWN OF CUMBERLAND CONTRACTOR: A.H. GROVER, INC. PROJECT MANAGER: DAN DIFFIN PERIOD ENDING: WED., 10 MAY 2018

PROJECT MANAGER: DAN DIFFIN				
AVERAGE FIELD FORCE				
Name of Contractor		Non- manual	Manual	Remarks
A.H. GROVER INC		1	2-4	On-site 05/07 through 05/09
NORTHEAST SAFETY (Flagging)		0	3	On-site 05/07 through 05/09
VISITORS				
Date	Name	Representing		Remarks
TYPICAL EQUIPMENT ON-SITE				
1-2 EXCAVATORS, 1 LOADER, 1 SWEEPER & 1 ROLLER (A.H. GROVER, INC.)				
CONSTRUCTION ACTIVITIES				
Mon., 05/07 – Mobilize equipment and personal				
Tues., 05/08 – Begin drainage structure and drainage pipe installation with CB 3 at STA 8+25				
Wed., 05/09– Continue drainage improvements toward Town Hall along with sidewalk prep.				
PROJECTED CONSTRUCTION ACTIVITIES				
Thurs., 05/10 – Continue drainage pipe installation toward Town Hall.				
Fri., 05/11 – Continue drainage pipe installation and drainage pipe installation toward Town Hall.				
Sat., 05/12 & Sun., 05/13 – No Work				
Mon., 11/14 – Complete drainage work and sidewalk prep at Town Hall entrance.				
Tues., 11/15 – Begin drainage structure improvements at STA 8+25 toward the rail road tracks.				
Wed., 11/16– Continue with drainage improvement work toward rail road tracks.				
QUALITY ASSURANCE:				
SME on-site to review overall progress, verify materials & quantities, and inspect erosion control measures.				
Sivil on-site to review overall progress, verify materials & quantities, and inspect crosion control measures.				

DISTRIBUTION:


- 1. Owner Town of Cumberland
- 2. Contractor A.H. Grover, Inc.
- 3. Engineer Sevee & Maher Engineers, Inc.
- 4. File

BY: Nick Thompson

TITLE: FIELD ENGINEER PAGE 1 OF 1 PAGE



\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0507-0509.docx May 10, 2017 Page 1 of 2



Photograph 4 - Wednesday, May 09th – Field inlet installation.

\\nserver\CFS\TCU\Tuttle Road\Construction\Weekly Reports\Photos\Weekly Photos 0507-0509.docx May 10, 2017 Page 2 of 2